

General Environmental Incident Summary

Incident: 1953 **Date/Time Notice:** 6/20/2013 1130 **DEM Incident No:**
Responsible Party: Weatherford
Date Incident: 6/20/2013 **Time Incident:** 1000 **Duration:**
County: Williams **Twp:** 154 **Rng:** 101 **Sec:** 1 **Qtr:** SW SW SW
Lat: 48.19040 **Long:** -103.61470 **Method:** Derived from TRS
Location Description: 3602 2nd Ave West

Submitted By: Tyler Dabney **Affiliation:**
Address:
City: **State:** **Zip:**

Received By:

Contact Person: Kelly Heller
3602 2nd Ave West
Williston, ND 58801

Distance Nearest Occupied Building: 75 Feet

Type of Incident: Contaminated Runoff

Description of Released Contaminant: Oil/Diesel contaminated water

Volume Spilled: 0.25 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Saturated soil contaminants were carried by rain water runoff from company property to a residential ditchline.

Risk Evaluation:

Little to no health hazards present.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 04 - water and soil

Potential Environmental Impacts:

Release immediately contained onsite
No Agency notification needed
No impacts likely

Action Taken or Planned:

Absorbent booms & pads were staked in place at all culvert locations to mitigate further contamination. Vac truck was hired to remove contaminated water from ditchline. Company front end loader & labor crew removed contaminated soil from street curb.

Wastes Disposal Location: Recovered water will be remediated via separator system on company premises. Contaminated soil will be stored in 55gal drum for removal by Safety-Kleen, an approved company vendor.

Agencies Involved: City of Williston

Updates

Date: 6/21/2013

Status: Reviewed; Followup Required

Staff: Roberts, Kris

Updated Volume:

Notes:

Release of crude contaminated water into residential ditch line. Follow-up is indicated to ensure that adequate cleanup was completed.

Date: 6/27/2013

Status: Inspected

Staff: Stockdill, Scott

Updated Volume:

Notes:

Spoke with Company Man about the incident he gave me the exact location and cause of the spill.

Arrived on Location at 3:45 pm on 6/27/2013.

Spill cleaned up appropriately with no present contaminant left at the location. Due to the urban nature of the incident location a very small amount was recorded.

Spoke with Company Contact at 1:26 pm on July 1, 2013.

They asked if anything else was needed regarding this incident. Due to the size of the spill and proper cleanup action taken no further review or action will need to be taken regarding this incident (#1953).